Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2918	((405/154.1,155,157,174-183) or (37/365,378,347,189,465,367, 464)).CCLS.	USPAT; USOCR	OR	OFF	2005/10/02 21:22
S1	1	("6371691").PN.	USPAT; USOCR	OR	OFF	2005/02/22 12:52
S2	7	("3722225" "3952532" "4063429" "4464082" "4785559" "4812078" "5467420").PN.	USPAT	OR	OFF	2004/07/13 16:53
S3	0	"6371691".URPN.	USPAT	OR	OFF	2005/04/05 10:19
S4	1960	((405/154.1,155,157,174-183) or (37/365,378,347,189,465,367, 464)).CCLS.	USPAT; USOCR	OR	OFF	2005/04/18 15:37
S5	14542	cable near5 (lay laying laid)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 17:50
S6	4475	S5 and (duct trench slit slot)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 17:51
S7	1462	S6 and (fill filler filling seal sealant sealer sealing)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 17:52
S8	737	S7 and (ground soil earth aphalt pavement paved paving roadway road)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 17:53
S9	1	("6371691").PN.	USPAT; USOCR	OR	OFF	2004/12/21 18:55
S10	0.	S9 and hdpe	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 18:55
S11	1	S9 and polyethylene	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 19:18
S12	0	S9 and "125"	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 19:05
S13	1	S9 and "20"	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2004/12/21 19:18

			т —			
S14	194	trench same (cable duct) same (spacer spacing)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/02/22 12:56
S15	1	("6807355").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/02/22 12:56
S16	1	"6371691".PN.	USPAT	OR	OFF	2005/04/05 10:19
S17	8	("3722225" "3952532" "4063429" "4464082" "4785559" "4812078" "5467420").PN. OR ("6371691").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/05 10:20
S18	. 3	S17 and spacer	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 10:46
S19	14986	cable same spacer	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 10:46
S20	218	S19 and "405"/\$.ccls.	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 10:50
S21	1631	"405"/\$.ccls. and spacer	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 10:51
S22	1413	S21 not S20	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:10
S23	1676	"138"/\$.ccls. and spacer	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:10
S24	1579	S23 not S21	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:32
S25	59565	(trench slot) same spacer	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:32
S26	12491	(trench slot) near6 spacer	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:32

	,				·	
S27	2339	S26 and (cable duct pipe)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:33
S28	280	S27 and ("fiber optic" optical)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:40
S29	68	trench same spacer same cable	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:46
S30	280	finzel-\$.in.	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 11:46
S31	36	finzel-lo\$.in.	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/05 13:26
S32	634	(405/154.1,157).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/04/05 13:26
S33	15	("2773512" "3335647" "3473339" "3713947" "3798743" "3818659" "3862479" "4030259" "4250675" "4332429" "4341007").PN. OR ("4554724"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/05 13:37
S34	2907	((405/154.1,155,157,174-183) or (37/365,378,347,189,465,367, 464)).CCLS.	USPAT; USOCR	OR	OFF	2005/10/02 21:22
S35	186	S34 and ((pull pulling pulled) near6 cable)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/18 15:42
S36	161	(remove removal removed removing replace replacement replacing replaced) same ("fiber optic cable") same (pull pulling pulled puller)	US-PGPUB; USPAT; USOCR; DERWENT	OR	ON	2005/04/18 15:43